



217/782-6761

Refer to: 0310000000 -- Cook County -- ILD070246137
Parkview Mobile Home Park/Hodgkins, Illinois
Superfund/HRS

March 16, 1987

Mr. Sam Eiserman
8783 Canary Lane
Hodgkins, Illinois 60525

RECEIVED

MAR 24 1987

Program
Support Section

Dear Mr. Eiserman:

This letter is to advise you that the Illinois EPA (IEPA) intends to conduct a site inspection of the above-referenced site during the week of May 25, 1987. Such an inspection will be conducted under the statutory authority of the Comprehensive Environmental Response, Compensation, and Liability Act of 1980 (CERCLA), and the Illinois Environmental Protection Act. These provisions permit the USEPA or IEPA to enter any establishment where "hazardous substances have been generated, stored, treated, disposed of, or transported from." Please respond in writing two (2) weeks of receipt of this letter if there is a problem with access to the site. If we do not hear from you within that time, it will be understood that we have access to the property. In addition, the CERCLA authority allows IEPA to collect samples of any hazardous substances or from any container during the inspection. At the time of the inspection, IEPA personnel intend to collect samples of surface water, soils and sediments. During the inspection, you will be provided the opportunity to receive split or duplicate samples. Please be prepared to provide appropriate sample containers.

IEPA has been duly authorized by USEPA to conduct inspections under the authority of CERCLA on behalf of the USEPA. A representative of IEPA will be contacting you in the near future to set a specific time within the week specified above for doing the inspection. The site inspection will be performed to determine the impact or potential impact on the environment of any hazardous substances which may exist at the site. A site inspection is subsequently reflected in a report, a copy of which may be requested by contacting this office. Screening via a site inspection is part of the process for identifying those facilities which may require remedial measures.

Individual sample points and number of samples to be taken have not, at this writing, been determined, however, exact information pertaining to such will be made available to you in ample time prior to our visit.

RECEIVED

MAR 24 1987





Page 2

In the meantime, if you have any questions regarding this matter, please contact Kenneth W. Corkill at 217/782-6760.

Sincerely,

A handwritten signature in cursive script that reads "Monte M. Nienkerk".

Monte M. Nienkerk
State Site Management Unit
Remedial Project Management Section
Division of Land Pollution Control

MMN:KC:st:1872g,52-53

cc: Don Josif, USEPA
Bill Child, DLPC
Jim Frank, DLPC
Division File
Maywood Region
Author